This drawing, specifications, and concepts contained here in are the sole property of Dart Aerospace, and may not be reproduced or used in any fashion without the prior written permission of Dart Aerospace Eugene, OR.

ASSY QTY B/O


Part #

C45-13-1

1 KEEPER BUSHING

REVISIONS									
REV	ECR	ECR DESCRIPTION			APPROVED				
3		AS DRAWN BY CANAM.	9/12/2012	RJC					
4		CH'D FROM Ø.624 +.001/000 TO Ø.62606256, HEAT TREAT FROM RC 45-48 TO RC 44-46.	6/18/2014	JAG	RJC				
4A		CH'D TITLE BLOCK WAS RED BARN IS DART. ADDED BAG & LABEL NOTE. CH'D TOLERANCE ON NON- CRITICAL DIMENSIONS.	8/14/2014	DPD	RW				

## SEE ATTACHED DEVIATION




Description

Material

4140

Ø3/4 X 1/2



**B/O INFORMATION OR SPECIFICATIONS** 



- NOTES:
  1. NICKEL PLATE .0004 .0006, BAKE AFTER PLATING.
- 2. BAG & LABEL WITH BATCH NUMBER.

DART								
KEEPER BUSHING								
C45-13-1 REV 4A								
MAT'L 4140			DRAWN BY:	CANAM				
		OTHERWISE SPECIFIED		D We	il			
.XXX ± .005		IONS ± 1/8	HEAT TREAT	RC 44-46				
VV ± 04		GLES ±.5°	FINISH	SEE NOTE 1				
1. BREAK ALL	SHARP EDG	ES .015 x 4	SPEC					
OR .015R 2. DIMENSION	AL LIMITO AD	DIVACTE	USED ON MODEL					
PLATING	AL LIMITS AP	PLT AFTER	•					
SCALE	2:1	DATE 5	/15/1997	SHEET 1 O	F 1			

Entered: Date:				SADT
	WORK ORDER NON-CONF	ORMANCE / ROUTE UPDATE		DAR
NCR No.			Route update only	
Job:	DISPOSITION	DEPARTMENT/PROCESS		
Part No. <u>C45 - 13 - 1 REV4</u> A	Rework Scrap Use-as-is	Skid-tube Cross tube  Machining Small Fab  Large Fab Finishing		Water Jet
Date: 20 19 - 05-21 Seque	nce #:	QTY Affected :		MRB (QSI042)
Description Work Orde	er Deviation	Dispositio	n	W (
MATERIAL WAS 4140 LI NICKEL PLATE	14-46 RC	THIS DEVIATION IS AC	CEPTABLE TO	Completed By
15 17-4 H900 NO FINISH REQUIRED	H, NO HEAT TREAT	FIT, FORM, AND FUNCTION WILL BE AS ORIGINALLY INTENDED		Lead hand / Supervisor  QC / QA Coordinator
Root Cause		FAULT CATEGORY		
Operator  Manufacturing Process  Equip/Tooling  Handling/Presservation  Material  Product Improvement	Pressure/Forced  Bending  Crushing  Cracks  Crimp/Kink/Ripple/Wave/Twist  Marks/Chatter  Mislabeled  ner/Details:	Contamination Misaligned/off center BOM/Route Broken/Damage/Defect Incomplete/Unclear Instructions Drill Holes Fit/Function	Power Loss/Surge Folio/Program Grain Direction Weld Wrong Stock Pulled Out of Sequence Off-set/Set-up	Positioned Wrong Outside Tolerance Drawing Finish Part Lost/Missing Misread